



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor 

Minerals Regulatory Program

Date of Report:
May 19, 2010

Mine Name: Ticaboo Stockpile Removal
Operator Name: Ucolo Exploration Corporation

Permit number: S/017/0001
Inspection Date: May 13, 2010
Time: 5:00 – 5:15 PM

Inspector(s): Wayne Western
Other Participants: none
Mine Status: ACT

Weather: Clear, 60s

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:


1. Permits, Revisions, Transfer, Bonds

The permit was transferred to Ucolo Exploration Corporation in July 2009. There are two separate Ucolo permits in the area both of which are called Ticaboo Stockpile Removal. The stockpiles on the west side are under permit S/017/0050, while the stockpile on the east is under permit S/017/0001. Note the permit number was changed from M/017/0001 to S/017/0001. The stockpiles were originally in the Tony M mine permit but were later taken out of the Tony M permit and assigned a small permit mine number when the acreage was reduced to 4 acres. A small mine is any mine under 5 acres.

Conclusions and Recommendations:

The Division should continue to monitor the site. Given the close location to the Tony M mine the Division's staff should be in the area at least once a year. Uranium prices are currently depressed so the owner will most likely not ship ore from the site until prices increase.

Inspector's Signature



Date:

5/19/2010

WHW

cc: Nancy Wolverson, Operator
Buzz Rakow, Hanksville BLM

O:\M017-Garfield\M0170001-TicabooStockpileRemoval\inspection\ins-05142010.doc